



USB CHARGER

Quick Guide // Kurzanleitung

Charging // Ladevorgang



1. First connect the USB CHARGER with the Lupine battery.
2. Then connect the USB CHARGER with the USB Port.
 - Ready or full
 - Charging



1. Zuerst den USB CHARGER mit dem Lupine Akku verbinden.
2. Anschließend den USB CHARGER mit dem USB Port verbinden.
 - Bereit oder voll
 - Ladevorgang





Attention! You can leave the USB CHARGER connected to the USB Port. However if you disconnect it from the USB Port, also disconnect it from the battery itself.



Obacht! Der USB CHARGER kann mit dem USB Port verbunden bleiben. Allerdings sollte der USB CHARGER vom Akku getrennt werden, wenn dieser nicht mehr über USB geladen wird.

Technical Data // Technische Daten



Input:
Charging Current:

USB Port
up to 1000 mA



Eingang:
Ladestrom:

USB Port
bis zu 1000 mA

EC Declaration of Conformity: www.lupine.de/ce/

EC Konformitätserklärung: www.lupine.de/ce/

Lupine lighting systems GmbH
Im Zwiesel 9
92318 Neumarkt

